



Gedling Bouncy Castle Hire – Bubble Machine Risk Assessment

Hazard	Who might be harmed?	Existing Control Measures	New Control Measures	Risk (1-5) 1 Low – 5 High	Harm (1-5) 1 Low – 5 High	Likelihood (1-5) 1 Low – 5 High
Electric Shock	All Users	PAT Test equipment, Cables checked before us	Bubbles to be directed away from electrical appliances and plug sockets. If outdoors unplug when raining.	1	5	1
Lifting	All Users	Employees deliver to site and manual handling trained	Unit not to be moved once sited.	1	3	1
Wet Floors – Slipping	All Users	Mats provided on hard surfaces such as wooden floor.	Adult Supervision at all times, follow rules in the safety guide provided.	3	3	2
Skin reaction to fluid	All Users	Water to be present on site. Advise that person washes fluid from skin.	Supply COSHH information with regards to the fluid used. All information provided in safety guide.	2	4	1
Fluid/Bubbles in the eyes	All Users	Clean water must be available from premises if required along with small shot glass to be used as an eye wash if needed.	Irrigate eyes thoroughly for 15 minutes. All information provided in safety guide.	2	5	1
Damages to clothing or possessions	All Users	Disclaimer wrote in Terms & Conditions of hire.	N/A	1	1	1



Gedling Bouncy Castle Hire – Bubble Machine Risk Assessment

Tripping over bubble machine	All Users	Hazard tape to be placed on the floor around where bubble machine is. Follow rules in safety guide.	Follow rules in safety guide about keeping 2 meters clear of the machine.	3	3	2
Choking on fluid or suffering with breathing difficulties	All Users	Water to be provided if needed to help people who swallow fluid.	Venue to provide first aid if needed and move person to safe area.	2	5	1
Other localised risks:	1.					
	2.					
	3.					
	4.					

The above information is based on manufacturers criteria and experience from extensive use of the equipment

Any other action required: If manned event ensure that operators follow all “Staff Information Pack & Safety Guide” as supplied.

Risk assessment carried out by:

Date:/...../.....

Signature: